

FIGURE 2:
Minimum width of Corridor
AS1428.1-2001

While a 1000 wide corridor may be accessible by most users, it clearly does not permit passing of wheelchair users by ambulant persons. Further, it creates difficulty for larger ambulant persons to pass each other.




FIGURE 2(a)




FIGURE 2(b)

Passing is difficult →




FIGURE 2(c)